

FIG. 2

RECEIVED

JUL 2 3 2002

Technology Center 2600





🗲 eDrowing Viewer - Pump2.eDw

ile View Help





3D Pointer

- 1. ALL BUSSES TO HAVE A 6' DRAFT
 2. ALL HOLES LABELED "TIC HOLE 6" HAVE A COMPOUND ANGLE
- 3. SEE 100-2032-000 FOR OTHER CASTING DIMENSIONS


RECEIVED


JUL 2 3 2002





SECTION A-A






How do I create an eDrawing?

Mouse position: 9.16,21.99

🖹 Start 🔀 🧲 📉 🗷 🥩 🗷 nbox Microsoft 🔾 Exploring — D\Ne... 🗛 AutoCAD 2000 — [... 🗗 eDr





RECEIVED JUL 2 3 2002 Technology Center 2600

FIG. 4







FIG. 5







How do I create an eDrawing?


Mouse position: 8.73,18.79

Stort 🔀 🗲 🗆 🔯 🗷 😿 😉 nbox Microsoft QExploring-D\Ne... AAutoCAD 200-[



7/29 eDrawing Viewer - D: \Opportunities\ForerunnerDemo\Level3\PUMP HOUSINGO.eDw File View Help Shaded D A 50 SECTION A-A RECEIVED JUL 2 3 2002 Technology Center 2600 How do I create an eDrawing?










FIG. 8











		1100
	RECEIVED JUL 2 3 2002 Technology Center 2699	🕤 untitled 🛛 📞 🔞 4: 35PM
		Mouse position: 9.16,21.99 AStort 图内图 图 INDox Microsoft图Exploring—D\NeAutoCAD 2000—BeDrawing Vie
		Mouse position:










Technology Center 2600









FIG. 15





RECEIVED

JUL 2 3 2002
Technology Center 2600

FIG. 16




FIG. 17






FIG. 18




FIG. 20





FIG. 19



RECEIVED

JUL 2 3 2002

Technology Center 2000






FIG. 22




FIG. 23






FIG. 24




FIG. 25








FIG. 26

A CONTRACTOR OF THE PARTY OF TH







FIG. 27








FIG. 29

27/29






FIG. 30

28/29






FIG. 31




FIG. 32